




**PROVIDE DEPENDABLE, SUSTAINED PROTECTION FOR ONLY PENNIES A DAY!**



**TARGET POLLUTION PHASE:**

**GERMS**

**INCLUDES:**



**Viruses, Bacteria, Biological Growth**

**CAN CAUSE:**

Biological Breeding Ground, Growth on Equipment Parts, Clogged Coils and Drip Pans, Equipment Circulates Germs, and May Cause Respiratory Conditions

## PAN TREATMENTS - LAST UP TO 6 MONTHS!

**Time-Release Drain Pan Treatments** are placed in the condensate drain pan between the coil and the drain opening, to intercept the path of the water to the drain. The blue polyester sock and polymer shell stay put in the drain pan until the system is maintained again next season. Stale standing water in your system drain pan can breed bacteria, mold and mildew, which can cause your HVAC system's drain pan to clog and overflow. Dirt & biological growth inside your heating and cooling system can lead to premature breakdowns, shorten the life of your system, and cause you to overpay on your utility bills. This can also aggravate asthma, allergies, and cause other health concerns.



### Two Size Options:

- **1-2 1/2 ton unit:** Part # - #PT1-2 1/2 ton (pack of 12)
- **3-5 ton unit:** Part # - #PT3-5 ton (pack of 12)

### ADVANTAGES

### BENEFITS

Keeps the water in the cooling coil drain pan free from slime and odor caused by biological growth in the standing water.	Helps prevent water leaks and clogged drains and eliminates fungus, mold, and mildew from the stale water.
The honeycombed outer layer holds the product intact and is only activated when it absorbs water.	Dependable, sustained time-released protection for just pennies a day!
The pan treatment is non-corrosive.	Prevents drain pan corrosion caused by aggressive chemicals used in other products.
Registered with the Environmental Protection Agency (EPA) 63281-2-80464.	Listed as safe to use while killing odor-causing bacteria and other biologicals.

**Website: [ElevatedIndoorAir.com](http://ElevatedIndoorAir.com)**

Phone: (239)-ELE-VATE (353-8283)